



Keys to Symbols

- BPM Horizontal
- BPM Vertical
- C Magnet
- Dipole Main Bending
- Dipole Trim
- Gate Valve
- Kicker
- Loss Monitor
- Quad Horizontally focusing
- Quad Vertically focusing
- Scanning Target
- Scintillator
- Septa
- SWIC or Multiwire
- Toroid 714

- I:V701 => 4 "C" Magnets
- I:Q703 => Q703 to Q709
- I:HV703 => 703 to 713
- I:HV F12 => F12 to F16
- I:QF12 => F12 to F17
- S:QP3 => QF18 to QF47
- S:HP3US => 17 to 34
- S:HP3DS => 35 to 49